


DIGITAL INDICATORS (STANDARD TYPE)




2504-101F



2504-10F
2504-101F

analog pointer



spindle lift knob is
included



- Reading in digital and analog
- Button function: on/off, zero, inch/metric conversion, measuring direction change, absolute/incremental measurement, switch resolution (for 2504-101F)
- Absolute system, data remains after power off
- CR2032 battery, automatic power off (time is adjustable)
- Data output
- Optional accessory: contact points

Code	Range	Resolution	Accuracy	Hysteresis	Maximum measuring force	Cap	Remark
2504-10F*	12.7mm/0.5"	0.01mm/0.0005"	20µm	10µm	1.5N	cannot lift	flat back
2504-101F*	12.7mm/0.5"	0.005mm/0.0005" (can switch to 0.01mm/0.0005")	10µm	5µm	1.5N	cannot lift	flat back

*Supplied with manufacturer inspection certificate