


HIGH PRECISION DIGITAL INDICATOR



2506-101F




- Reading in digital and analog
- Button function: on/off, zero, data preset, tolerance Go and No-Go display, inch/metric conversion, measuring direction change, max./min./TIR measurement, absolute/incremental measurement
- Absolute system, data remains after power off
- CR2032 battery, automatic power off (time is adjustable)
- Data output
- Optional accessory: contact points


analog pointer



max./min./TIR



alarm when over tolerance



spindle lift knob is included



Code	Range	Resolution	Accuracy	Hysteresis	Maximum measuring force	Cap	Remark
2506-101F*	12.7mm/0.5"	0.001mm/0.00005"	3μm	2μm	1.5N	cannot lift	flat back

* Supplied with manufacturer inspection certificate