

MAGNETIC FIELD INDICATORS

- Indicate the residual magnetism left in ferrous parts
- Rugged and portable design



JCZ-10

SPECIFICATION

Code	JCZ-5	JCZ-10	JCZ-20	JCZ-30	JCZ-50
Range	5Gs	10Gs	20Gs	30Gs	50Gs
Graduation	0.5Gs	1.0Gs	2.0Gs	3.0Gs	5.0Gs
Unit	Gs				
Accuracy	±10%FS				
Working environment	temperature: -10°C~50°C; humidity: <80%RH, no condensation				
Storage environment	temperature: 0°C~40°C; humidity: <80%RH, no condensation				
Dimension	Ø58×26mm				
Weight	63g				