




ATTENTION: RECHARGEABLE BATTERY,
FOR 500 HOURS CONTINUOUS WORKING

DATA
OUTPUT

ABSOLUTE SYSTEM




2503-101F



Unit: mm

HIGH PRECISION DIGITAL INDICATOR

max./min./TIR



analog pointer

analog pointer



alarm when over tolerance

over upper limit



within tolerance



over lower limit



spindle lift knob is
included



- Reading in digital and analog
- Button function: on/off, zero, data preset, tolerance Go and No-Go display, inch/metric conversion, measuring direction change, max./min./TIR measurement, absolute/incremental measurement
- Automatic power off (time is adjustable)
- Absolute system, data remains after power off
- Data output
- Power: rechargeable Li-battery
- Optional accessory: contact points

Code	Range	Resolution	Accuracy	Hysteresis	Maximum measuring force	Cap	Remark
2503-101F*	12.7mm/0.5"	0.001mm/0.00005"	3μm	2μm	1.5N	cannot lift	flat back

*Supplied with manufacturer inspection certificate