

NO NEED TO SET
ZERO BEFORE USE

LEVEL BUBBLES




4955-3




4955-4




4955-5



4955-3



4955-4



4955-5

Unit: mm

■ No need to set zero before use

Code	Range	Graduation	Accuracy	Working temperature	Base diameter	Base type
4955-3	0-3°	1°	±0.2°	-20°C~50°C	Ø30mm	Stainless steel, without mouting hole
4955-4	0-4°	1°	±0.2°	-20°C~40°C	Ø90mm	Aluminum alloy, with mouting holes
4955-5	0-5°	2°	±0.4°	-20°C~50°C	Ø80mm	Aluminum alloy, with mouting holes